

## **Product Change Notification**

Notice Issue Date: Jun, 21, 2023

Description: LDO9864BFH5 controller IC ST7548T EOL, the substitution will

become LDO9864B2FH0. LDO9864B2FH0 controller IC is ST7578i.

Affected Model: BO9864BFPHH252j\$ \( \) BO9864BFPNH252j\$ \( \)

BO9864B-FPHNH\$

Substitute new products: BO9864B2-FPHNH\$(with controller IC ST7578i)

FSTN positive/transreflective (FPC with down side

attached).

Unit Dimension Change: NO Electronic Feature Change: NO

Function Difference: NO (software and hardware are compatible)

**Planning Changing Time**: Immediately after the current stock running out.

UJ Light appreciated your support of our products and we will continue to do our best to support and work with you. If there have any further questions, please feel free to contact your service salesperson. Thank you

Best Regards,
UJ Light sale and Marketing team